

PRODUCT SAFETY RECALL

TRAILPRO TRAILERS

**Models: Trailpro 8x4 Tradesman – Model no. TP5,
Trailpro 8x5 Tandem – Model no. TP8.**

Sold at Bunnings stores nationwide from 1st January 2006 – 12th October 2018



Defect

The trailer's drawbar may break at the front attachment bolts to the chassis, leading to failure and detachment of the drawbar. Heavy or frequent commercial use may accelerate this hazard.

Hazard

Detachment of the drawbar poses significant safety hazards to other road users and bystanders.

What to do

Check the identification plate on the side of the trailer's drawbar (as shown in the photo) to confirm the model number. If it's an affected model, **stop using the trailer** in a loaded capacity immediately.

Contact details

If you have one of these trailers, or are in doubt, please contact Bunnings customer service centre on 0800 561 109. For more information, please go to www.bunnings.co.nz/returns/recalls

Please note that NZTA-appointed inspectors have been instructed to not issue WoFs on affected models until the repair is completed.

**See www.recalls.govt.nz for
other New Zealand consumer product recalls**

BUNZ19218